

## VIST A CORPORATE CENTER




A TRANQUIL SPACE HIGH ABOVE SAN ANTONIO'S NORTHWEST CORRIDOR WITH UNIQUELY EXPANSIVE VIEWS, VISTA IS A PLACE WHERE MINDS WILL BE INSPIRED AND NEW IDEAS WILL BE CONCEIVED.







# EXPERIENCE THE SPACE TO THINK DIFFERENTLY.







## BUILT TO INSPIRE.

VISTA CORPORATE CENTER, an extraordinary new development, is located in the heart of San Antonio's burgeoning northwest submarket. From the impressive porte cochère entrance to the floor-to-ceiling glass walls that create seamless indoor/outdoor transitions, this state-of-the-art facility is unlike anything we've ever seen.

VISTA CORPORATE CENTER is full of smart design surprises.

By using filtered light, natural views and contemporary concepts in greenscaping, VISTA combines high visual impact with a healthy workspace. Incorporating natural elements not only reduces operation costs but lowers stress and inspires happiness. Research studies show conclusively that buildings with natural elements incorporated into the design have a dramatic effect on the well-being of its occupants. VISTA delivers a sense of tranquility that can lead to more productivity, higher job satisfaction and a higher sense of place.

Aside from the awe-factor, VISTA CORPORATE CENTER's stunning green wall and rain wall help cool the building in the summer and add insulation in the winter. The roof collects rain water that feeds the building and makes VISTA's unique amenities both sustainable and economical. The climate-designed open space, fitness area, bistro café and gardens create a communal atmosphere.

#### A TRANQUIL WORK SPACE WILL IMPACT THE BOTTOM LINE.



- SUPERIOR EXPERIENCE of moving from the car to your office from covered garage, through a lush garden and waterfall promotes a sense of well-being and serenity.
- High-quality environment **24/7 CONTROLLED ACCESS** for tenants.
- Slender structural steel design makes smaller column footprints resulting in **MORE EFFICIENT USE OF THE SPACE.**
- **A GRAND ENTRANCE** The 30-foot tall living wall creates a breathtaking entrance, leaving an impression on both tenants and visitors alike.
- **FORM AND FUNCTION** the sleek, modern exterior canopy design routes rainwater to indigenous landscaped planters below.
- A stunning look-through waterfall feature from garden courtyard to lobby is **A BOLD AND ELEGANT STATEMENT**.
- Bistro café and fitness gym amenities foster **A COMMUNAL ATMOSPHERE**.





LOCATION	13805 IH-10 W, San Antonio, Texas 78249	LOBBY FINISHES	Patterned stone tile
RENTABLE SQUARE FEET	150,735± RSF		Stone wall tile with water Wood ceilings
TOTAL OFFICE FLOORS	Five (5)		Recessed lighting with ac
FLOOR PLATE SIZES	FLOOR PLATE SIZESLevel 1: 31,846± RSFLevel 2: 30,829± RSF	FITNESS CENTER	Locker rooms with showe State-of-the-art fitness eo Adjacent to café and out
	Level 3: 29,470± RSF Level 4: 29,295± RSF Level 5: 29,295± RSF	CORRIDOR FINISHES	Carpet Painted walls TechZone Ceiling System
COMMON AREA FACTOR	Single Tenant: 1.08 Multi-Tenant: 1.125		12" x 48" recessed lightin
PARKING GARAGE	4:1,000 RSF Total: 600 spaces Accessible (ADA): 12 spaces	Large scale porcelain tile Painted drywall ceiling Recessed lighting Solid surface vanity top	
LEASE DEPTH	42'-0" as measured from core wall to exterior wall	EXIT STAIR FINISHES	Painted walls Painted metal stairs and h
CEILING HEIGHT	9'-0"		Concrete treads (pan fille
MULT-TENANT CORRIDOR WIDTH	5'-6" (minimum)	PASSENGER ELEVATORS	Two (2) 3000 lb High-Sp One (1) 4000 lb High-Spe
FOUNDATION SYSTEM	Straight-shaft pier foundation		Brushed stainless door ar
STRUCTURAL SYSTEM	Structural Steel Frame with composite steel framed floors with concrete slabs over metal deck	HVAC SYSTEM	Five (5) 80 Ton VAV Roo
DESIGN LOADS	Typical Floor Live Load: 50 psf Ceiling and Mechanical Load: 7 psf Lobby Area Live Load: 100 psf Mechanical Area Live Load: 125 psf Storage Area Live Load: 125 psf		Each RTU will supply air to Tenant Improvements to loop as follows: a) ductwo external insulation and b) with internal insulation ex
EXTERIOR WALLS	Two colors of precast concrete wall panels with curtainwall glazing		Tenant Improvements to
ROOF SYSTEM	PVC single-ply 60 mil Sika Sarnafil RhinoBond Roofing System		server perimeter zones (c Tenant Improvements to (quantity and location to
			Summer 74°F and 50% R

**INDOOR DESIGN** Summer 74°F and 50% RH **CONDITIONS** Winter 72°F and no humidity control

## **VISTA DETAILS**

erfall feature

accent chandelier

wers equipment utdoor seating

m with tegular edge tile ceiling ting

le

d handrails illed) with broom finish

Speed MRL KONE Passenger EcoSpace™ peed MRL KONE Service Elevator and Hoistway frames

oof Package Units (one RTU per floor)

r to an externally insulated primary duct loop on each floor

to provide for all ductwork downstream of the primary duct work to VAV boxes will be galvanized sheet metal with b) ductwork downstream of VAV boxes will be sheet metal except last 8' (max) before the diffuser can be flexible duct

o provide for fan powered VAV boxes with electric heat to (quantity and location to be determined by Tenant)

o provide for VAV boxes to serve interior zones to be determined by Tenant)

ENERGY MANAGEMENT SYSTEM	Building energy management system will utilize direct digital controls supported by central PC operation and floor-by-floor panels	EMERGENCY POWER SUPPLY	Battery I commor
	Tenant Improvements to provide for thermostats, lighting controllers and expansion of floor-by-floor panels as required to support Tenant work		Battery I
LIFE SAFETY SYSTEMS	Fully addressable and expandable fire alarm system with devices covering building common areas	TELEPHONE SERVICE	Incoming telephor backboa
	Tenant Improvements to provide for fire alarm devices and expansion of the system as required to support Tenant work		Two (2) telephor backboa
	Automatic fire sprinkler system for light hazard occupancy as follows: a) fully recessed sprinkler heads in building common areas and b) sprinkler heads turned up at maximum spacing in Tenant areas		Cables to data roo
	Tenant Improvements to provide for reconfiguring fire sprinkler system in Tenant area as required to support Tenant work	DOMESTIC WATER SYSTEM	Domesti serve the
ELECTRICAL SERVICE	2500 KVA pad mounted transformer, 480 volt, three phase, 4 wire main electrical service		
	3000A main switchboard with main disconnect and ground fault protection		
	2500A Busway through each floor provides for larger equipment installation if required by tenant		
	Power capacity provided as follows: a) 3.0 watts psf connected for 208/120 volt receptacle load to support Tenant power demands and b) 1.1 watts psf lighting load (per energy code requirements) to support Tenant power demands		
	Electrical rooms on every level, including the following equipment: a) one (1) 125A, 42 circuit, 480/277 volt, three phase, four wire panel for lighting power b) one (1) 400A, 42 circuit. 480/277 volt, four wire panel for mechanical/plumbing power c) one (1) 112.5 KVA step down transformer feeding one 400A, 42 circuit, 208/120 volt, four wire panel for receptacle power		
	Tenant Improvements to provide for additional panels and circuiting to support Tenant work		

## BUILT TO INSPIRE.

y back-up for all emergency lighting to serve the building on areas

ry back-up coast down/recall for elevators

ing telephone/data service shall be terminated in main none/data room located on the first level, painted plywood oard on two primary walls

2) 4" conduit risers will provide access to intermediate one/data rooms on each floor, painted plywood oard on one primary wall

s to be pulled between main and intermediate telephone/ ooms by service provider or Tenant contractor

stic water pump package and electric water heater to the building common areas

## **AMENITIES MAP**

POSITIONED IN SAN ANTONIO'S DYNAMIC NORTHWEST SUBMARKET.


## **INGRESS & EGRESS MAP**



#### 1. Quarry Hofbrau at The Rim 2. Chick Fil-A 3. TGIFridays 4. Stone Werks Big Rock Grille 5. Islamorada Fish Co 6. Maggiano's Little Italy 7. BJ's Restaurant & Brewhouse 8. Taste Crepes & More 9. Mimi's Café 10. Sustenio 11. Piatti 12. Tiagos Cabo Grille 13. Mona Lisa's Pizzeria 14. The General Public 15. JUICEssential 16. Zoes Kitchen 17. Cosi 18. Red Robin Gourmet Burgers 19. Freddy's 20. Bob's Steak & Chop House 21. The Bistro 22. 54th Street Grill and Bar 23. Great American Grill 24. PF Changs 25. Va Bene Pizzeria Napoletana 26. Whiskey Cake 27. Grimaldi's Pizzeria 28. Brio Tuscan Grille 29. Perry's 30. Yard House 31. The Cheesecake Factory 32. Olive Garden 33. Longhorn Steakhouse 34. Red Lobster 35. Tacos N Salsa 36. Applebee's 37. Chuy's 38. Cheddar's Casual Café 39. Urban Brick Pizza at The Rim 40. Bowl & Barrel at The Rim 41. Ruth's Chris Steakhouse at Eilan 42. Russo's Coal Fired Italian Grill 43. Which Wich at The Rim

#### LODGING

44. Courtyard San Antonio Six Flags 45. Residence Inn San Antonio 46. La Cantera Hill Country Resort 47. Staybridge Suites NW S 48. Comfort Inn Fiesta at Six Flags 49. Drury Inn & Suites 50. La Quinta Inn & Suites 51. Sleep Inn & Suites at Six Flags 52. Super 8 San Antonio/Fiesta 53. Eilan Hotel & Spa



#### BANKING

54. IBC Bank 55. BBVA Compass 56. Security Service Federal Credit Union 57. Synergy Federal Credit Union 58. RBFCU 59. United SA Federal Credit Union 60. Frost Bank 61. Woodforest National Bank 62. Bank of America 63. Chase Bank

#### ENTERTAINMENT

64. Top Golf


65. Six Flags Fiesta Texas 66. Shops at La Cantera 67. Santikos Palladium IMAX 68. Bowl & Barrel 69. iFLY San Antonio (coming soon) 83. Ultra Fitness and Spa 70. La Cantera Golf Club 71. Palmer Golf Course 72. Dominion Country Club


#### **GROCERY & PHARMACY**

73. HEB 74. Walmart Supercenter 75. Walmart Neighborhood Market 76. Target 77. Costco

#### **HEALTH & WELLNESS**

78. REI 79. Life Time Fitness 80. ChampionFit Gym 81. Bedlam CrossFit 82. Camp Gladiator 84. CrossFit Lobo 85. Gold's Gym 86. UTSA Recreation 87. Academy Sports






## **ENTRANCE DETAIL**


TRUE CLASS A+ BUILDING TOTALING 150,735± RSF

















## FLOOR PLAN - LEVEL 2: 30,829± RSF

FULL OF SMART DESIGN SURPRISES.




Å





## FLOOR PLAN - LEVEL 3: 29,470± RSF










### FLOOR PLAN - LEVEL 4: 29,295± RSF

FULL OF SMART DESIGN SURPRISES.



Å







 $\checkmark$ SAN ANTONIO



#### VISTA-SA.COM

13805 IH-10 W, SAN ANTONIO, TX 78249

For more information about leasing opportunities at VISTA CORPORATE CENTER please call 210.341.1344

Russell T. Noll, CCIM, CPM® russell.noll@transwestern.com



The information provided herein was obtained from sources believed reliable; however, Transwestern makes no guarantees, warranties or representations as to the completenes. The presentation of this property is submitted subject to errors, omissions, change of price or conditions, prior sale or lease, or withdrawal without notice

or accuracy thereof.